Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 8/28/2012 (Half), 8/29/2012, 8/30/2012	Man Days: 2.5
Inspection Unit: Jacksonville	•
Location of Audit: Jacksonville	
Exit Meeting Contact: Rodger Camerer	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Donald Hankins	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

CONSTRUCTION INFORMATION			
Location of Construction:		Construction Performed By:	
Old Route 67 northwest of Jacksonville	e, Illinois.	Construction was performed by an Ameren	Illinois Crew.
Contractor Foreman:	The work was performed	The work was performed by Ameren and not a contractor.	
Operator Inspector:	Bob Roth, Gas Quality A	Bob Roth, Gas Quality Assurance	
	Person(s) On	Job Site	
Description of Construction:			
 Installing a new 3/4 inch steel service li	ine from the tapping tee to a f	farm tap set.	

SERVICE INSTALLATION		Status
192.55	Steel	Yes
General Comment:	<u>.</u>	
3/4 inch steel service line.		
192.59	PE	No
General Comment:	<u> </u>	•
No plastic pipe was installed.		
192.59	Other	No

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
No other installation was done.		
192.619,192.621,192.623	MAOP	Not Applicable
General Comment:		
The MAOP of the line is 60#.		
192.5	Class location :	Not Applicable
General Comment:		
This service installation is in a class 2 area.		
192.53	Are components qualified for use?	Satisfactory
General Comment:		
All components were labeled properly.		
192.63(a)(2)	Pipe Size :	Not Applicable
General Comment:		
The pipe Size was 3/4 inch steel		
192.55,192.59	Specification :	Not Applicable
General Comment:		
The specification is API 5LX steel pipe.		
192.55,192.59	Manufacturer :	Not Applicable
General Comment:		
The pipe manufacturer is ERW.		
192.55,192.59	Pipe Grade :	Not Applicable
General Comment:		
The grade is X42 pipe.		
192.55,192.59	Wall Thickness :	Not Checked
General Comment:		
Wall thickness was .188		
192.63	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
General Comment:		
Markings were properly placed on pipes and fittings.		
192.227	Welder qualification date:	Not Applicable
General Comment:		

AMEREN ILLINOIS COMPANY/8-30-2012

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

The welding qualification date was 7-11-12		
192.227	Welder's Name:	Not Applicable
General Comment:		
Stan Fanning was the welder.		
192.225,192.275,192.277,192.279,192.283	Is pipe joined in accordance with approved written procedures?	Satisfactory
General Comment:		
Pipe was installed by proper procedures.		
192.285	Date of Qualification :	Unsatisfactory
General Comment:		
Plastic pipe was no installed.		
192.285	Joiner's name:	Not Applicable
General Comment:		
No plastic pipe was installed.		
192.455	Is buried metallic pipe coated?	Satisfactory
General Comment:		
The steel pipe was coated.		
192.455(a)(1)	Is cathodic protection being provided?	Satisfactory
General Comment:		
Cathodic protection is being provided by anodes.		
192.455(a)(1)	Is cathodic protection being provided? By Anodes:	Yes
General Comment:		
Cathodic protection was provided by anodes.		
192.455(a)(1)	Is cathodic protection being provided? By Rectifier:	No
General Comment:		
This pipe is not being protected by rectifiers.		
192.461	Does coating meet 192.461?	Satisfactory
General Comment:		
The coating on the pipe met the requirements.		
192.461(c)	Is coating inspected just prior to being installed in the ditch?	Satisfactory
General Comment:		
The coating was inspected prior to being placed into the	ne ditch.	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

192.479	Are above ground facilities cleaned and coated or jacketed as needed?	Satisfactory
General Comment:	<u> </u>	
All above ground piping was clean and painted.		
192.467	Are pipelines electrically isolated from other underground metallic structures?	Satisfactory
General Comment:	<u> </u>	
There were no other metallic structures in the area.		
192.319	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
General Comment:		
The pipe was back filled to prevent damage.		
192.321(c)	Is plastic pipe installed as to minimize shear and tensile forces?	Not Applicable
General Comment:	<u> </u>	
No plastic pipe was installed on this job.		
192.321	Does plastic pipe have means of locating while underground?	Not Applicable
General Comment:	<u> </u>	
No plastic pipe was installed on this job.		
192.325	Are required clearances from underground structures being maintained?	Satisfactory
General Comment:		
No other ground structures are in this area.		
Is required cover being obtained for the s	ervice line?	Satisfactory
General Comment:		
The proper cover was maintained during installation	1.	
192.503	Are general testing requirements being met?	Satisfactory
General Comment:	<u> </u>	
Pressure test were at 100 PSIG.		
192.517	Are records being made of strength and leak tests?	Satisfactory
General Comment:		
Records were made of the pressure test.		
192.807	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory

AMEREN ILLINOIS COMPANY/8-30-2012

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
The OQ records were inspected for qualit	ications.	
192.805(c)	Were non-qualified personnel being "directed and observed" by a qualified individual?	Not Applicable
General Comment:	·	
No non-qualified personnel were doing ar	ny work on this job.	
192.805(c)	Were span of control limitations being followed?	Not Applicable
General Comment:		
No span of control had to be followed.		
Was a Protocol 9 (Form 15) Completed?		No
General Comment:		
A protocol 9 was not made during this au	dit.	
192.614	Were One Call Notifications performed as required?	Satisfactory
General Comment:	· · · · · · · · · · · · · · · · · · ·	
The operator had a Julie one call notificat	ion.	
192.614	Dig Ticket #	Not Applicable
General Comment:		
The Julie dig number was A002330622		
192.383(b)	Is an EFV installed on any new or replaced service line serving a single-family residence?	Satisfactory
General Comment:		

Unless otherwise noted, all code references are to 49CFR Part 192.

If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.